


Shark

OWNER'S GUIDE

GI435C 55



FEATURES

- | | |
|--|--|
| 1 Stainless Steel Soleplate | 8 Water Level Window |
| 2 Water Inlet Door | 9 Pivot Cord |
| 3 Atomizer Spray Button | 10 Fabric Settings |
| 4 Electronic Temperature Control | 11 Temperature Indicators |
| 5 Spray Nozzle | 12 Power Light |
| 6 Variable Steam/Self-Clean Control | 13 Auto-Off Light |
| 7 X-Tended Steam Burst™/ Steam Burst Button | 14 Anti-Drip Function (not shown) |
| | 15 Built-In Anti-Calcium Filter (not shown) |

TECHNICAL SPECIFICATIONS: 120 Volts, 60 Hz., 1600 Watts



This appliance has a polarized plug (one blade is wider than the other). As a safety feature, this plug will fit into a polarized outlet only one way. If the plug does not fit fully into the outlet, reverse the plug. If it still does not fit, contact a qualified electrician. Do not attempt to defeat this safety feature.

ONE YEAR LIMITED WARRANTY

EURO-PRO Operating LLC warrants this product to be free from material defects and workmanship for a period of one (1) year from the date of purchase when utilized for normal household use, subject to the following conditions, exclusions and exceptions.

The liability of EURO-PRO Operating LLC is limited solely to the cost of the repair or replacement of the unit at our option. This warranty does not cover normal wear of parts and does not apply to any unit that has been tampered with or used for commercial purposes. This limited warranty does not cover damage caused by misuse, abuse, negligent handling or damage due to faulty packaging or mishandling in transit. This warranty does not cover damage or defects caused by or resulting from damages from shipping or repairs, service or alteration to the product or any of its parts, which have been performed by a repair person not authorized by EURO-PRO Operating LLC.

If your appliance fails to operate properly while in use under normal household conditions within the warranty period, you may return the complete appliance and accessories with proof of purchase and date, freight prepaid. For customer service support, call **1-800-798-7398** or visit our website at www.sharkclean.com.

If the appliance is found by EURO-PRO Operating LLC to be defective, in EURO-PRO Operating LLC's sole discretion, we will repair or replace it free of charge. Proof of purchase date and check made payable to EURO-PRO Operating LLC in the amount of \$9.95 to cover the cost of return shipping and handling must be included.

This warranty is extended to the original purchaser of the unit and excludes all other legal, implied and/or conventional warranties. The responsibility of EURO-PRO Operating LLC if any, is limited to the specific obligations expressly assumed by it under the terms of this Limited Warranty. In no event is EURO-PRO Operating LLC liable for incidental or consequential damages to anyone of any nature whatsoever. Some states do not permit the exclusion or limitation of incidental or consequential damages, so the above may not apply to you.

This Limited Warranty gives you specific legal rights, and you may also have other rights which vary from state to state or province to province.


***IMPORTANT:** Carefully pack item to avoid damage in shipping. Be sure to include proof of purchase date and to attach a tag to item before packing including your name, complete address and phone number with a note giving purchase information, model number and what you believe is the problem with the item. We recommend you insure the package (as damage in shipping is not covered by your warranty). Mark the outside of your package "ATTENTION CUSTOMER SERVICE". We are constantly striving to improve our products, therefore the specifications contained herein are subject to change without notice.

BEFORE FIRST TIME USE

- Before using your iron for the first time, please remove all the packaging material.
- When you turn on the iron for the first time it might emit an odor for the first ten minutes. This is because the materials used in making the iron are heating up. The odor is safe and should not re-occur after the initial heating.

USING YOUR IRON

- Fill water carefully into the water tank without going over "Max" line. Make sure the water inlet cover is closed to avoid spilling.
- Plug in the iron into any 120V AC polarized electrical outlet.
- Set the desired fabric/temperature by pressing the Electronic Temperature Control.
- The temperature indicator light on the LED Display Panel will flash when the iron is heating up. The green light will stop flashing and stay on when the iron reaches the preset temperature.
- Turn the variable steam control to select high or low steam setting. Select "0" on the steam control for dry ironing. You can now start ironing.
- Use the steam burst/X-tended steam burst button to remove stubborn wrinkles. Turn the button counter-clockwise to the burst of steam position (for quick bursts of steam); or turn the button clockwise to the X-tended steam burst position (for prolonged bursts of steam). Press the button in the steam burst position once or several times if in the X-tended steam burst position to prime the pump. Allow an interval of 3 seconds between each burst. Overuse of the steam burst may cause water spitting or weak steam performance.
- The steam burst feature also works in the vertical position. This is especially useful to remove wrinkles from hanging clothes, delicate garments and other fabrics. Hold the iron in the upright position several inches away from the article.
- Use the atomizer spray to moisten the fabric to tackle tough wrinkles, if necessary.



ANTI-DRIP FEATURE

- The anti-drip feature is built in to this iron. It prevents water spitting when the temperature is too low.
- Steam cannot be produced if the soleplate is not hot enough. It may result in water spitting or leaking from the soleplate. The anti-drip feature reduces water dripping and leaking when ironing at low temperatures.

ANTI-CALCIUM

- This iron has built in the anti-calcium system that prolongs the life of the iron.
- If you have very hard water, we recommend using distilled water instead of tap water.

ELECTRONIC MULTI POSITION AUTO-OFF

- This iron is equipped with an electronic auto-off feature that switches the iron off if it has been idle in the sideways, flat or upright positions for 7-9 minutes.
- The auto-off light will flash in red on the LED display when the iron is in auto-off mode. To turn the iron back on, just gently rock the iron back and forth several times until the "Power ON" green light is re-illuminated. Reset the temperature to the desired setting; wait for the green light to stop flashing. The iron might have to warm up for a minute if the auto-off feature was activated for an extended time.

SELF-CLEANING

- Fill the water tank to the "MAX" level. Do not overfill.
- Stand the iron on its heel, standing up on a protected surface and plug into the electrical outlet
- Set the Electronic Temperature Controls to "•••" setting. Wait until the green light stops flashing. The iron is now on the preset temperature.
- Hold the iron horizontally over the sink. Turn and hold the steam control all the way to the right to the SELF CLEAN position.
- Move the iron back and forth. Boiling water and steam will now be ejected from the holes in the soleplate. Use caution when doing this as the water and the steam are hot enough to cause burns.
- Continue step 21 until the impurities and scale are washed away.
- Empty any excess water from the tank. Don't touch the hot surfaces, water or steam because injury may occur.
- Turn the steam control to "0".
- Place the iron in upright position and let it cool down.

USEFUL TIPS

- Read all garment care labels before you start ironing. You can also test the temperature of the iron on a hem or an inside seam.
- Iron similar fabrics together and in sequence of synthetic fibers acrylic, nylon, silk/wool, polyester, and cotton/linen. This will reduce the need to adjust the temperature frequently.

IRONING GUIDE

FABRIC TYPE	Acrylic, or nylon	Silk or wool	Polyester	Cotton or linen	Please note that the symbol above on the label of your garment means that THE ARTICLE CANNOT BE IRONED
LED DISPLAY PANEL	LOW	•	••	•••	
STEAM CONTROL	0	0	0		
BURST OF STEAM	NO	NO	NO	YES	
SPRAY	YES	YES	YES	YES	

STORAGE AND CARE

- Always turn the variable steam control to "0" after you have emptied the water tank.
- Allow the iron to cool down before putting it away.
- Place the iron in the upright position during heating up, cooling down and storage.
- Avoid any sharp material contacting the soleplate.
- Every two weeks, clean the exterior of the iron with a damp cloth and wipe dry.
- If you use spray starch, wipe the soleplate occasionally with a soft, damp cloth to prevent deposit build-up.
- If the iron hasn't been used in a few weeks, hold the iron horizontally and allow steaming for 2 minutes before ironing.

ALWAYS REMEMBER

- Unplug the iron from the electrical outlet before pouring water into the iron.
- Always empty the water in the iron after each use.
- Never iron or steam clothes while they are being worn.

- Be very careful when filling the iron with water. Injuries may occur if the hot metal parts, hot water or steam are contacted.

TROUBLE SHOOTING

The iron doesn't heat up	Iron should be plugged into a 120V AC electric outlet only. Make sure the plug is securely in the socket. Temperature setting might be too low. Try turning to a higher setting. Auto-off feature is activated.
An odor is being emitted from the new iron or small particles are coming out	This is normal. Follow the instructions for first-time use and allow iron to steam through 2-3 fillings and press the steam burst button occasionally to eliminate small white particles.
Iron doesn't steam	Water tank may be empty or water level is very low. Add water. Make sure the fabric/temperature setting and the variable steam control are correctly set. For maximum steam, set "MAX" on steam control and the temperature setting should be set on "•••." Steam control is set on "0." The soleplate is not hot enough and the anti-drip feature switches off the steam. Always allow the iron to reach the selected temperature with the variable steam control setting at "0." For more steam, turn temperature dial to a higher setting and the steam control to "MAX." If the temperature setting and steam control settings are correct and there is no steam, gently move the iron left or right a couple of times. Move the Steam Control from "0" to "MAX" a few times.
Water droplets coming from steam vents.	Variable Steam Control lever may be set in "self clean" position. Align the lever to the "0" to "Max" steam setting. Iron may not be hot enough. Set temperature to "•••" position. Always allow iron sufficient time to heat up before activating the variable steam control. Overuse the steam burst. Allow more time between each burst.

IMPORTANT SAFETY INSTRUCTIONS

READ ALL INSTRUCTIONS BEFORE USING YOUR IRON

When using your iron, basic safety precautions should always be followed, including the following:

- Use iron only for its intended use.
- To protect against risk of electrical shock, do not immerse the iron in water or other liquids.
- DO NOT** yank cord to disconnect from outlet. Grasp plug and pull to disconnect.
- DO NOT** allow cord to touch hot surfaces. Let iron cool completely before putting away. Loop cord loosely around iron when storing.
- Always disconnect iron from electrical outlet when filling with water, emptying, or when not in use.
- DO NOT** operate iron with a damaged cord, or after the iron has been dropped or damaged in any manner. To avoid the risk of electric shock, do not disassemble the iron. Return to EURO-PRO Operating LLC for examination, repair or adjustment. Incorrect reassembly can cause the risk of electric shock when the iron is used.
- Close supervision is necessary for any appliance being used by or near children. **DO NOT** leave iron unattended while connected or on an ironing board.
- Burns can occur from touching hot metal parts, hot water or steam. Use caution when you turn a steam iron upside down; there may be hot water in the reservoir.
- Never use or rest iron on an unstable surface.
- While the iron is hot, never set iron on an unprotected surface - even if it is on its heel rest.
- Always store your iron standing upright, not on the soleplate. If stored face down, even the smallest amount of moisture will cause the soleplate to corrode and stain.
- This appliance is for household use only.

CAUTION! TO PREVENT ELECTRIC SHOCK OR OTHER INJURY, before filling the iron with water, make sure that the plug is removed from the outlet.

WARNING: Never fill the iron with fabric conditioner, starches or any other solution, as these will damage the steam mechanism. Do not use contaminated water.

CAUTION! TO AVOID FIRE, never leave iron unattended while it is plugged in.

CAUTION! TO PREVENT ELECTRIC SHOCK, never use the iron in a location where it can fall or be pulled into water or another liquid. If the iron falls into water or other liquid, unplug it immediately. DO NOT reach into the water or liquid.

WARNING: Never use scouring pads, abrasive or chemical cleaners, or solvents to clean the exterior or soleplate of your iron. Doing so will scratch and/or damage the surface.

CAUTION! DO NOT aim iron at face, towards yourself, or anyone else while using or adjusting steam. Burns or serious injury may occur.

SPECIAL INSTRUCTIONS


- To avoid a circuit overload, do not operate another high-wattage appliance on the same circuit.
- If an extension cord is absolutely necessary, use a 15-ampere cord. Cords rated for less amperage may overheat. Use care to arrange the cord so that it cannot be pulled or tripped over.

SAVE THESE INSTRUCTIONS

Shark

GUIDE DU PROPRIÉTAIRE

GI435C 55



CARACTÉRISTIQUES

- 1 **Plaque en acier inoxydable**
- 2 **Couvercle de l'orifice d'eau**
- 3 **Bouton de pulvérisation atomiseur**
- 4 **Contrôle électronique de température**
- 5 **Jet de vaporisation**
- 6 **Vapeur variable et levier de commande d'auto nettoyage**
- 7 **Bouton X-Tended Steam Burst^{MC}/ Bouffée de vapeur**
- 8 **Fenêtre du niveau d'eau**
- 9 **Cordon pivotant**
- 10 **Régages du tissu**
- 11 **Indicateurs de la température**
- 12 **Voyant d'alimentation**
- 13 **Lumière d'arrêt automatique**
- 14 **Fonction antigoutte** (non illustré)
- 15 **Filtre anticalcium intégré** (non illustré)

SPÉCIFICATIONS TECHNIQUES : 120 volts, 60 Hz, 1 600 watts



Cet appareil possède une fiche polarisée (une lame de contact est plus large que l'autre). À titre de caractéristique de sécurité, cette fiche ne pourra être insérée que d'un seul côté, dans une prise électrique polarisée. Si la fiche ne s'insère pas complètement dans la prise murale, retournez la fiche. Si cela ne fonctionne toujours pas, contactez un électricien accrédité. Ne tentez pas de contourner cette caractéristique de sécurité.

GARANTIE LIMITÉE DE UN AN

EURO-PRO Operating LLC garantit ce produit contre toute **défectuosité matérielle** ou de main d'œuvre pour une période d'un (1) an à compter de la date d'achat originale, lorsqu'utilisé dans le cadre d'un usage domestique normal, sujet aux conditions, exclusions et exceptions suivantes.

La responsabilité d'EURO-PRO Operating LLC est limitée au coût des réparations ou du remplacement de l'appareil, à sa convenance. Cette garantie ne couvre pas l'usure normale des pièces et ne s'applique pas aux appareils ayant été altérés ou utilisés à des fins commerciales. Cette garantie limitée ne couvre pas les dommages causés par une mauvaise utilisation, l'abus, la négligence lors de la manipulation, un emballage inadéquat ou la mauvaise manipulation en transit. Cette garantie ne couvre pas les dommages ou défauts causés par ou résultant du transport, des réparations, de l'entretien ou de l'altération du produit ou à ces pièces effectuée par un réparateur non-autorisé d'EURO-PRO Operating LLC.

Si votre appareil ne fonctionne pas comme il le devrait lors d'un usage domestique normal pendant la période de garantie, vous pouvez le retourner complet avec ses accessoires, frais préaffranchis. Pour contacter le service d'assistance à la clientèle, appelez au **1-800-798-7395** ou visitez notre site Internet sur www.sharkclean.com.

S'il s'avérait que l'appareil possède une **défectuosité**, EURO-PRO Operating LLC le réparera ou le remplacera sans frais, à sa seule discrétion. Une preuve d'achat incluant la date ainsi qu'un chèque au nom d'EURO-PRO Operating LLC au montant de 9,95 \$ pour couvrir les frais d'expédition de retour et la manutention doivent être inclus.

Cette garantie est couverte pour l'acheteur initial du produit et exclue toute autre garantie légale, implicite ou conventionnelle. La responsabilité d'EURO-PRO Operating LLC, s'il y en a une, se limite aux obligations spécifiques exprimées sous les termes de cette garantie limitée. En aucun cas, EURO-PRO Operating LLC ne peut être tenu responsable d'incidents ou dommages indirects à quiconque et de toute nature que ce soit. Certaines provinces n'autorisent pas l'exclusion ou la limitation de dommages circonstanciels ou conséquents, auquel cas cette disposition ne s'appliquerait pas.

Cette garantie limitée vous confère des droits juridiques spécifiques, et d'autres droits légaux vous sont peut-être disponibles, variant d'un état à l'autre d'une province à l'autre.


***IMPORTANT :** Emballez soigneusement l'appareil pour éviter tout dommage lors du transport. Assurez-vous de joindre la preuve d'achat et d'attacher à l'appareil une étiquette mentionnant votre nom, adresse complète ainsi que le numéro de téléphone, de même que l'information concernant l'achat, le numéro de modèle et le problème, selon vous, de l'appareil. Nous vous recommandons d'assurer votre colis (puisque les dommages lors du transport ne sont pas couverts par la garantie). Indiquez sur l'extérieur de votre colis « ATTENTION SERVICE À LA CLIENTÈLE ». Nous essayons constamment d'améliorer nos produits, donc les clauses contenues dans ce document peuvent changer sans préavis.

AVANT LA PREMIÈRE UTILISATION

- 1 Avant d'utiliser votre fer pour la première fois, veuillez retirer tout le matériel d'emballage.
- 2 Lorsque vous faites fonctionner le fer pour la première fois, une odeur pourrait se dégager pendant les dix premières minutes de fonctionnement. Il s'agit de la surchauffe des matériaux utilisés pour la fabrication du fer. L'odeur est sans danger et ne devrait pas réapparaître après le chauffage initial.

UTILISATION DE VOTRE FER À REPASSER

- 3 Remplissez soigneusement d'eau le réservoir, sans toutefois dépasser la ligne « Max ». Assurez-vous que le couvercle de l'orifice d'eau est fermé afin d'éviter toute éclaboussure.
- 4 Le fer peut être branché dans toute prise électrique polarisée de 120V AC.
- 5 Réglez à la température ou au tissu désiré en appuyant sur le contrôle électronique de la température.
- 6 L'indicateur lumineux de température sur le panneau d'affichage à DEL clignotera pendant le réchauffement du fer. La lumière verte cessera de clignoter et restera allumée lorsque le fer aura atteint la température réglée.
- 7 Tournez le cadran de vapeur variable afin de sélectionner un réglage de vapeur élevé ou bas. Pour un repassage à sec, réglez le cadran de vapeur à « 0 ». Vous pouvez maintenant commencer à repasser.
- 8 Utilisez le bouton de bouffée de vapeur/bouffée de vapeur prolongée pour supprimer les plis rebelles. Tournez le bouton dans le sens antihoraire à la position bouffée de vapeur, (pour obtenir des bouffées de vapeur rapides); ou tournez le bouton dans le sens horaire à la position de bouffée de vapeur prolongée (pour des bouffées de vapeurs prolongées). Appuyez à une ou plusieurs reprises sur le bouton de jet de vapeur si le bouton est à cette position afin d'amorcer la pompe. Laissez un intervalle de 3 secondes entre chaque jet. Une surutilisation de la vapeur peut causer des éclaboussures d'eau ou une mauvaise performance de la vaporisation.
- 9 L'option de bouffée de vapeur fonctionne aussi en position verticale. L'option de jet de vapeur est particulièrement utile pour effacer les plis des vêtements suspendus, des vêtements délicats et autres tissus. Tenez le fer en position verticale, à plusieurs centimètres de distance de l'article.
- 10 Si nécessaire, utilisez le vaporisateur atomiseur pour humidifier le tissu où des plis rebelles sont présents.



FONCTION ANTI-GOUTTE

- 11 La fonction anti-goutte est intégrée à ce fer à repasser. Elle empêche l'éclaboussement d'eau lorsque la température du fer est trop basse.
- 12 Aucune vapeur ne sera produite si la plaque n'est pas suffisamment chaude. L'eau pourrait vous éclabousser ou s'échapper par la plaque. L'option anti-goutte réduit les gouttes et fuites d'eau lors du repassage à basses températures.

ANTI-CALCIO

- 13 Ce fer possède un système anticalcium intégré qui prolonge la durée de vie de votre fer.
- 14 Si votre eau est très dure, nous vous recommandons d'utiliser de l'eau distillée plutôt que l'eau du robinet.

ARRÊT AUTOMATIQUE MULTIPPOSITIONS ÉLECTRONIQUE

- 15 Ce fer est équipé d'une option d'arrêt automatique électronique qui éteint le fer si celui fonctionne au ralenti depuis 7 à 9 minutes, qu'il ait été déposé sur le côté, en position verticale ou horizontale.
- 16 La lumière rouge d'arrêt automatique clignotera sur l'affichage à DEL lorsque le fer est en mode d'arrêt automatique. Pour remettre le fer en marche, balancez-le doucement de l'avant vers l'arrière à quelques reprises jusqu'à ce que la lumière verte « En marche » s'allume. Réajustez la température au réglage désiré; attendez que la lumière verte cesse de clignoter. Le fer devra peut-être réchauffer pendant quelques minutes si l'arrêt automatique a été activé pendant une période prolongée.

AUTO NETTOYAGE

- 17 Remplissez le réservoir d'eau au niveau « MAX ». Ne pas trop remplir.
- 18 Déposez le fer sur ses talons, sur une surface protégée et branchez-le dans une prise électrique.
- 19 Réglez la Commande de température électronique à « ●●● ». Attendez que le témoin lumineux vert cesse de clignoter. Le fer a maintenant atteint la température préréglée.
- 20 Tenez le fer en position horizontale au-dessus de l'évier. Tournez et tenez le cadran de contrôle de vapeur complètement à droite, à la position AUTONETTOYAGE.
- 21 Balancez le fer de l'avant vers l'arrière. L'eau bouillante et la vapeur seront évacuées par les orifices situés dans la plaque de base. Soyez prudent lors de cette opération car l'eau et la vapeur sont suffisamment brûlantes pour causer des brûlures.
- 22 Poursuivez avec l'étape 21 jusqu'à ce que toutes les impuretés et le tarte aient été nettoyés.
- 23 Videz toute eau excédentaire du réservoir. Ne touchez pas les surfaces chaudes, l'eau ou la vapeur car des blessures pourraient survenir.
- 24 Tournez le Cadran de contrôle de vapeur à « 0 ».
- 25 Déposez le fer en position debout et laissez-le refroidir.

CONSEILS UTILES

- 26 Lisez toutes les étiquettes d'entretien de vêtements avant de commencer votre repassage. Vous pouvez aussi tester la température du fer sur un ourlet ou une couture intérieure.
- 27 Repassez les tissus semblables ensembles en débutant par les fibres synthétiques, le nylon, la soie et la laine, le polyester, le coton et le lin. Cela vous évitera de devoir ajuster fréquemment la température.

GUIDE DE REPASSAGE

TYPE DE TISSU	Acrylique ou nylon	Soie ou laine	Polyester	Coton ou lin	Prendre note que le symbole ci-dessus, lorsque présent sur l'étiquette de votre vêtement, signifie que CET ARTICLE NE DOIT PAS ÊTRE REPASSÉ
PANNEAU D'AFFICHAGE À DEL	LOW	●	●●	●●●	
COMMANDE DE VAPEUR	0	0	0		
JET DE VAPEUR	NON	NON	NON	OUI	
VAPORISATEUR	OUI	OUI	OUI	OUI	

RANGEMENT ET SOINS

- 28 Tournez toujours la commande de vapeur variable à « 0 » après avoir vidé le réservoir d'eau.
- 29 Laissez le fer refroidir avant de le ranger.
- 30 Déposez le fer en position verticale pour le faire réchauffer, refroidir et le ranger.
- 31 Évitez que la plaque ne vienne en contact avec tout objet pointu.
- 32 Une fois par deux semaines, l'extérieur du fer doit être nettoyé avec un linge humide et essuyez-le ensuite.
- 33 Si vous utilisez de l'amidon en vaporisateur, essuyez la plaque occasionnellement avec un linge humide pour empêcher toute accumulation de dépôts.
- 34 Si le fer n'a pas été utilisé depuis quelques semaines, tenez le fer en position horizontale et laissez la vapeur s'évacuer pendant environ 2 minutes avant de repasser.

RAPPELEZ-VOUS TOUJOURS

- 35 Débranchez le fer de la prise électrique avant de verser l'eau dans le fer.
- 36 Après chaque utilisation, videz l'eau restante dans le fer à repasser.
- 37 Ne jamais repasser ou vaporiser des vêtements pendant qu'ils sont portés.
- 38 Soyez prudents lorsque vous remplissez le fer avec de l'eau. Des blessures pourraient survenir si vous venez en contact avec des pièces métalliques chaudes, l'eau chaude ou la vapeur.

GUIDE DE DÉPANNAGE

Le fer ne chauffe pas.	Le fer doit être branché dans une prise électrique de 120 volts CA seulement. Assurez-vous que la fiche est sécuritairement branchée dans la prise de courant. L'ajustement de température est peut-être trop bas. Essayez un réglage plus élevé. L'option d'arrêt automatique est activée.
-------------------------------	---

Une odeur ou de petites particules s'échappent du nouveau fer.	Cette situation est normale. Suivez les instructions pour la première utilisation et laissez le fer produire de la vapeur pendant 2 ou 3 remplissages. Appuyez occasionnellement sur le déclencheur pour éliminer les particules blanches.
---	---

Le fer ne produit pas de vapeur.	Le réservoir d'eau est peut-être vide ou le niveau d'eau est très bas. Ajoutez de l'eau. Assurez-vous que l'ajustement de tissu ou de température et de commande de vapeur variable sont ajustés correctement. Pour une vapeur maximale, réglez la commande de vapeur à « Max » et le réglage de température doit à « ●●● ». Le cadran de commande de vapeur est ajusté à « 0 ».
---	--

La plaque n'est pas suffisamment chaude et la caractéristique antigoutte éteint la vapeur. Laissez toujours le fer attendre la température sélectionnée avec l'ajustement de commande de vapeur variable réglé à « 0 ». Pour plus de vapeur, tournez le cadran de température à l'ajustement le plus haut et la commande de vapeur à « MAX ».

Si l'ajustement de température et de vapeur sont adéquats et qu'aucune vapeur n'est produite, déplacez doucement le fer de la gauche vers la droite à quelques reprises. Déplacez le cadran de commande de vapeur de « 0 » à « Max » à quelques reprises.

Gouttes d'eau s'échappent des orifices de vapeur.	Le levier de commande de vapeur variable est peut-être réglé à la position « Auto nettoyage ». Réglez le levier de vapeur de la position « 0 » à « Max ».
--	---

Le fer n'est peut-être pas assez chaud. Ajustez la température à la position « ●●● ». Laissez toujours suffisamment de temps au fer pour réchauffer avant d'activer la commande de vapeur variable.

Sur-utilisation du jet de vapeur. Laissez plus de temps entre chaque jet de vapeur.

REV - 100421